



REPLACEMENT SHEET

FIG.1



REPLACEMENT SHEET

FIG.2



REPLACEMENT SHEET

FIG.3






FIG.4



REPLACEMENT SHEET

FIG.5



REPLACEMENT SHEET

FIG.6 (a)






FIG.6 (b)




REPLACEMENT SHEET

FIG.7



REPLACEMENT SHEET

FIG.8



REPLACEMENT SHEET

FIG. 9





FIG.10



REPLACEMENT SHEET

FIG.11 (a)






FIG.11 (b)



TORQUE CONVERTER CHARACTERISTIC MAP

REPLACEMENT SHEET

FIG.12



REPLACEMENT SHEET

FIG.13






FIG.16



REPLACEMENT SHEET

FIG.14



REPLACEMENT SHEET

FIG.15





FIG.17



REPLACEMENT SHEET

FIG.18 (a)






FIG.18 (b)




REPLACEMENT SHEET

FIG.19



REPLACEMENT SHEET

FIG.20



REPLACEMENT SHEET

FIG.20

